

KENTUCKY HISTORIC RESOURCES  
INDIVIDUAL SURVEY FORM  
(KHC 2002-1)

COUNTY Lewis  
RESOURCE # Lw-59  
RELATED GROUP #       
EVALUATION S  
SHPO EVALUATION U  
DESTROYED     

For instruction, see the Kentucky Historic Resources Survey Manual.

1. NAME OF RESOURCE (how determined): 5 / Kirkendall House

2. ADDRESS/LOCATION:

Poplar Flat Road, north side, approx. .75 miles down road from intersection with AA Highway  
Herron Hill, KY. 41189

3. UTM REFERENCE:

Quad. Name: Charters

Date: 1991 / Zone: 17 / Accuracy: A

Easting: / 2 / 8 / 1 / 7 / 4 / 9

Northing: 4 / 2 / 7 / 4 / 0 / 0 / 7

4. OWNER/ADDRESS:

Kirkendall Family  
Rt. 2 Box 380  
Tollesboro, KY. 41189

5. FIELD RECORDER/AFFILIATION:

Kate Carothers/ Environment & Archaeology, LLC.

6. DATE RECORDED:

8-12-05

7. SPONSOR:

Cellco Partnership d/b/a Verizon Wireless

8. INITIATION: 3 / Review & Compliance

Herron Hill PSC/ Collins cell site

9. OTHER DOCUMENTATION/RECOGNITION:

     Survey      HABS/HAER  
     KY Land      Local Land  
     NR      NHL

Other:

Report Reference

10. ORIGINAL PRIMARY FUNCTION: 0 / 1 / A /  
Single family home

11. CURRENT PRIMARY FUNCTION: 9 / 9 / V /  
Vacant

12. CONSTRUCTION DATE: 4 / c. 1900-1920 estimated  
/ / / / / documented

13. DATE OF MAJOR MODIFICATIONS:

/ /  
/ /

14. CONSTRUCTION METHOD/MATERIAL:

W 3 / Frame      original  
/ / / subsequent

15. DIMENSIONS:

Height stories 1.5 Width bays 3 Depth bays 2

16. PLAN:

K      / Central-passage plan, single pile      first  
/ /      second  
/ /      third

17. STYLISTIC INFLUENCE:

/ / ; / first  
/ / ; / second  
/ / ; / third

18. STYLE DEVELOPMENT:

R      / first      / second      / third

19. FOUNDATION:

TYPE MATERIAL  
2 / Continuous R/ Poured concrete original  
/ / / replacement

20. PRIMARY WALL MATERIAL:

1 / Weatherboard original  
/ / replacement

21. ROOF CONFIGURATION/COVERING:

CONFIGURATION COVERING  
A      / Gabled, side 7 / Standing-seam metal original  
/ / / replacement

22. CONDITION: P      / Poor

23. MODIFICATION: 2 / Moderate alteration

24. NEGATIVE FILE #:      /      /     

Write resource # on back of all prints.



COMMENTS/HISTORICAL INFORMATION:

Located on Poplar Flat Road, this property is a c. 1900-1920 one-and-a-half story frame dwelling resting on a poured concrete foundation, with a side-gabled standing-seam metal roof and 2/2 double-hung sash wood windows. The front porch appears to have been added later, and rests on a concrete block foundation with tree saplings serving as supports for the shed-style standing-seam metal roof. At the rear of the dwelling are two one-story later additions. One addition is frame, with a front-gabled standing-seam metal roof and jalousie windows, and the other is a lean-to addition behind the frame addition, clad in an undetermined material. The property is owned by the Kirkendall family, and is currently vacant and in poor condition.



25. SUPPORT RESOURCES: SITE PLAN KEY      FUNCTION      CONSTRUCTION DATE      METHOD MATERIAL

26. SITE PLAN (Complete if #25 was answered).

27. MAP (Scan or attach copy of map showing exact location of resource)

